




et of summer water. We'd have to go down and pull [the bulkheads] out, even in the night and make preparations for this two hundred-second et of extra water. Then the flume would already be soaked up for it was only a little ways from the lower side of either sand gate, or I mean bulkhead. And we had twenty of those to take out.




Ice Conditions at Ring Stations 421-427 Looking Southeast



Ice Condition on "Peach Tree Trestle" (No. 2 Siphon Area, Rings 352-364) Looking Southeast



Chief of Party, John E. Mackay and Crew Running Centerline Survey and Old Flume at Ring Station 544



Inspection Tour of Old Flume by Engineers of Utah Power and Light Company and Morrison-Knudsen Co. and Olson